

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-021900**Date Inspected:** 15-Mar-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 1500**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 300**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Mr. Sha Zhi**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector,Baskar Govindarajan, was present during the times noted above for observations relative to the work being performed.

Bay #16

This QA Inspector observed the following work in progress

Flux Cored Arc Welding (FCAW)

Weld joint- 084/ 085, Located on Crash Barrier E2-SB34-001. Welder is identified as 222394. ZPMC Quality Control Inspector (QC) is identified as Liu Tao. The welding variables recorded by QC appeared to comply with the WPS-B-T-2132-ESAB.

Weld joint- 126, Located on Crash Barrier W2-SB32A-002. Welder is identified as 206294. ZPMC Quality Control Inspector (QC) is identified as Liu Tao. The welding variables recorded by QC appeared to comply with the WPS-B-T-2132-ESAB.

Weld joint- 019, Located on Crash Barrier E2-SB23-002. Welder is identified as 062092. ZPMC Quality Control Inspector (QC) is identified as Liu Tao. The welding variables recorded by QC appeared to comply with the WPS-B-T-2332-ESAB.

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

Weld joint- 131, Located on Crash Barrier W2-SB18-003. Welder is identified as 055742. ZPMC Quality Control Inspector (QC) is identified as Liu Tao. The welding variables recorded by QC appeared to comply with the WPS-B-T-2132-ESAB.

Weld joint- 128, Located on Crash Barrier, W5-SB14B-001. Welder is identified as 201074. ZPMC Quality Control Inspector (QC) is identified as Liu Tao. The welding variables recorded by QC appeared to comply with the WPS-B-T-2132-ESAB.

Weld joint- 039, Located on Crash Barrier, E2-SB23-001. Welder is identified as 048625. ZPMC Quality Control Inspector (QC) is identified as Liu Tao. The welding variables recorded by QC appeared to comply with the WPS-B-T-2133-ESAB.

Shielded Metal Arc Welding (SMAW)

Weld joint- 001, Located on Crash Barrier E2-SB23-002. Welder is identified as 053753. ZPMC Quality Control Inspector (QC) is identified as Liu Tao. The welding variables recorded by QC appeared to comply with the WPS-B-P-2113.

Weld joint- 066, Located on Crash Barrier E2-SB36-001. Welder is identified as 201861. ZPMC Quality Control Inspector (QC) is identified as Liu Tao. The welding variables recorded by QC appeared to comply with the WPS-B-P-2113.

Weld joint- 069, Located on Crash Barrier E2-SB24-001. Welder is identified as 201905. ZPMC Quality Control Inspector (QC) is identified as Liu Tao. The welding variables recorded by QC appeared to comply with the WPS-B-P-2113.

Bay #19

This QA Inspector observed the following work in progress,

Flux Cored Arc Welding (FCAW)

Weld joint- 038, Located on Bike path BK4B1-001. Welder is identified as 058792. ZPMC Quality Control Inspector (QC) is identified as Peng Wen Jan. The welding variables recorded by QC appeared to comply with the WPS-B-T-2132-ESAB.

Weld joint- 044, Located on Bike path BK5A1-002. Welder is identified as 062783. ZPMC Quality Control Inspector (QC) is identified as Peng Wen Jan. The welding variables recorded by QC appeared to comply with the WPS-B-T-2132-ESAB.

Weld joint- 038, Located on Bike path BK4A1-013. Welder is identified as 062749. ZPMC Quality Control

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

Inspector (QC) is identified as Peng Wen Jan. The welding variables recorded by QC appeared to comply with the WPS-B-T-2132-ESAB.

For further information see below pictures:-

Unless otherwise noted, all work observed on this date appeared to be in general compliance with the applicable contract documents.



Summary of Conversations:

No relevant Conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Thomas Hu (15002048250), who represents the Office of Structural Materials for your project.

Inspected By:	Baskar,Govindarajan	Quality Assurance Inspector
Reviewed By:	Clifford,William	QA Reviewer
